

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, 17766
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

N. 0° 25' W., bet. secs. 26 and 27.

Ascend over S. slope, through scattering timber and dense undergrowth.

11.40 Ridge, bears N. 85° W. and S. 50° E., also gravelled road, 15 lks. wide, bears S. 85° E., and W.; desc. over N. slope.

34.70 Ravine, drains N. 70° E.; asc. over SE. slope.

39.52 The cor. of secs. 22, 23, 26, and 27, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd.

T 25 S	R 4 W
S 22	S 23
S 27	S 26

1957

from which bearing trees mkd. by Zirpel, Roseberry, and Corbin

A yew, 14 ins. diam., bears N. 66 1/2° E., 66 lks. dist., with healed blaze.

A cedar, 19 ins. diam., bears S. 50 1/4° E., 90 lks. dist., with healed blaze.

A maple, 14 ins. diam., bears S. 45 1/4° W., 97 lks. dist., with scribe marks R4W S27 visible on partially healed blaze.

A hemlock, 19 ins. diam., bears N. 53 1/2° W., 65 lks. dist., with scribe marks R4W S22 BT visible on partially healed blaze.

and a new bearing tree

A cedar, 3 ins. diam., bears S. 29° W., 52 lks. dist., mkd. X BT.

The corner is located at the end of a fence line extending N.

Land, mountainous.

Soil, stony clay.

Timber, fir, cedar, yew, hemlock, madrone, undergrowth hazel, vine maple, poison oak, and salal.

From the 1/4 sec. cor. of secs. 23 and 26, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd.

T 25 S	R 4 W
1/4	S 23
	S 26

1957

from which the remains of bearing trees mkd. by Claude Kerr, Registered Land Surveyor, No. 2125, in 1951