

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, **17769**
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

and a bearing tree mkd. by Vernon Tracy, Deputy County Surveyor, in 1965

A fir, 14 ins. diam., bears S. 12 1/2° W.,
148 lks. dist., with healed double blaze.

The corner is located 12 lks. E. of a fenceline extending N. and S.

N. 1° 27' E., beginning new measurement.

Descend over NE. slope.

1.15 Creek, 1 lk. wide, course W.; asc. over SW. slope.

5.40 Spur, slopes W.; desc. over broken NW. slope.

19.80 Ravine, drains W.; asc. over S. slope.

30.70 Top of ascent, slopes NW.; desc. over N. slope.

40.46 The cor. of secs. 14, 15, 22, and 23, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 2 ins above the ground, with brass cap mkd.

T 25 S R 4 W

S 15	S 14
S 22	S 23

1957

from which bearing trees mkd. by Zirpel, Roseberry, and Corbin

A fir, 19 ins. diam., bears N. 30 1/4° E.,
79 1/2 lks. dist., with healed blaze.

A fir, 24 ins. diam., bears S. 36 1/4° E.,
25 lks. dist., with healed blaze.

A fir, 22 ins. diam., bears S. 64 1/4° W.,
115 1/2 lks. dist., with healed blaze.

A fir, 17 ins. diam., bears N. 41 1/2° W.,
104 1/2 lks. dist., with healed blaze.

Land mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, oak, madrone, and maple;
undergrowth, poison oak, arrowwood, hazel, vine maple,
and young timber.

From the cor. of secs. 13, 14, 23, and 24.

N. 89° 31' W., bet. secs. 14 and 23.

Descend over NW. slope, through heavy timber and dense undergrowth.

4.35 Creek, 3 lks. wide, course N.; asc. over NE. slope.

18.50 Ridge, bears N. 40° E. and S. 40° W.; also gravelled road, 15 lks. wide, bears same; desc. over broken NW. slope.