

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

17770

CHAINS

40.14

The 1/4 sec. cor. of secs. 14 and 23, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 10 ins. above the ground, with brass cap mkd.

T 25 S R 4 W

1/4 $\frac{S\ 14}{S\ 23}$

1957

from which the remains of an original bearing tree

A cedar stump, 36 ins. diam., bears N. 60° E.,
8 lks. dist., no marks visible on decayed
blaze.

and a bearing tree mkd. by James Byron, Deputy County Surveyor, in 1956

A cedar, 25 ins. diam., bears S. 63 1/2° W.,
127 lks. dist., with a healed double blaze.

and a new bearing tree

A yew, 12 ins. diam., bears N. 67° W.,
124 lks. dist., mkd. 1/4 S 14 BT.

The corner is located on the right bank of Norris Creek,
5 lks. wide, course N. 5° W.

N. 88° 09' W.; beginning new measurement.

Ascend over SE. slope.

18.95

Spur slopes N. 40° E.; desc. over NW. slope.

20.19

The W 1/16 sec. cor. of secs. 14 and 23, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd.

W 1/16 $\frac{S\ 14}{S\ 23}$

1957

from which bearing trees mkd. by Zirpel, Roseberry, and Corbin

A fir, 16 ins. diam., bears N. 16 1/2° W.,
37 lks. dist., with healed blaze.

A cedar, 18 ins. diam., bears S. 63 3/4° E.,
19 1/2 lks. dist., with healed blaze.

N. 88° 17' W., beginning new measurement.

Descend over NW. slope.

20.27

The cor. of secs. 14, 15, 22, and 23.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, yew, oak, madrone, and maple; undergrowth, salal, vine maple, arrowwood, poison oak, and young timber.