

County Surveyor's Record, Douglas County, Oregon

17771 Dependent Resurvey, Portion of the Subdivisional Lines,
T. 25 S., R. 4 W., Willamette Meridain, Oregon

CHAINS

From the 1/4 sec. cor. of secs. 27 and 34, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mdk.

T 25 S R 4 W
1/4 $\frac{S 27}{S 34}$
1957

from which the remains of an original bearing tree

A cedar stump, 12 ins. diam., bears S. 55 1/2° W.,
12 lks. dist., with BT visible on opened
blaze.

and bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1955

A cedar, 36 ins. diam., bears N. 18 1/4° E.,
33 lks. dist., with scribe marks 1/4 S27 CS BT
visible on partially healed double blaze.

A fir, 24 ins. diam., bears S. 72° W.,
41 lks. dist., with healed double blaze.

and bearing trees mkd. by Zirpel, Roseberry, and Corbin

A cedar, 24ins. diam., bears N. 41° E.,
47 lks. dist., with scribe marks 1/4 S27 BT
visible on partially healed blaze.

A fir, snag, 18 ins. diam., bears S. 39 1/2° W.,
48 lks. dist., with healed blaze.

Corner is located 5 lks. N. of a fence line extending E. and W.

S. 87° 19' W., bet. secs. 27 and 34.

Ascend over SE. slope, through scattering timber and dense undergrowth.

- 1.80 Dirt road, 15 lks. wide, bears N. 15° E. and S. 15° W.
- 6.15 Spur, slopes S.; desc. over SW. slope.
- 9.35 Dirt road, 15 lks. wide, bears N. and S.
- 13.95 Creek, 3 lks. wide, course S.; asc. over broken SE. slope.
- 20.24 The W 1/16 sec. cor. of secs. 27 and 34, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mdk.

W 1/16 $\frac{S 27}{S 34}$
1957

from which the remains of the bearing trees mkd. by Zirpel, Roseberry, and Corbin