

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, 17772  
 T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears S.  $1/2^\circ$  E., 27 lks. dist.,  
 no marks visible on downed fir alongside.

A fir, 22 ins. diam., bears N.  $20^\circ$  W., 26 lks.  
 dist., with healed blaze.

and a new bearing tree

A cedar, 13 ins. diam., bears S.  $58^\circ$  E., 34 lks.  
 dist., mkd. W  $1/16$  S34 BT.

S.  $87^\circ 23'$  W., beginning new measurement.

Ascend over broken SE. slope.

2.05 Dirt road, 15 lks. wide, bears N. and S.

20.34 The cor. of secs. 27, 28, 33, and 34, monumented with an  
 iron post, 2  $1/2$  ins. diam., firmly set, projecting 4 ins.  
 above the ground, with brass cap mkd.

T 25 S	R 4 W
S 28	S 27
S 33	S 34
1957	

from which the remains of the original bearing trees

A sawed fir stump, 14 ins. diam., bears N.  $40^\circ$  E.,  
 18 lks. dist., with healed blaze.  
 (Record, N.  $42 1/2^\circ$  E.)

A sawed fir stump, 48 ins. diam., bears S.  $35^\circ$  E.,  
 28 lks. dist. with healed blaze.

A sawed fir stump, 26 ins. diam., bears S.  $67^\circ$  W.,  
 26 lks. dist., no marks visible on an opened  
 blaze.

and the remains of the bearing trees mkd. by Zirpel,  
 Roseberry, and Corbin

A cedar stump, 15 ins. diam., bears N.  $26 1/2^\circ$  E.,  
 31 lks. dist., with scribe marks T25S R4W S27 BT  
 visible on partially healed blaze.

A cedar, 28 ins. diam., bears S.  $74 1/2^\circ$  E., 43  $1/2$  lks.  
 dist., with healed blaze.

A cedar, 26 ins. diam., bears N.  $3 1/4^\circ$  W., 109 lks.  
 dist., with healed blaze. (Record, 100 lks.)

and bearing trees mkd. by Vernon Tracy, Deputy County  
 Surveyor, in 1965

A cedar, 13 ins. diam., bears N.  $80^\circ$  E., 35 lks.  
 dist., with healed double blaze.

A cedar, 17 ins. diam., bears S.  $28^\circ$  W., 73 lks.  
 dist., with healed double blaze.

The corner is located in a fence line extending N. and S.