

County Surveyor's Record, Douglas County, Oregon

17775

Dependent Resurvey, Portion of the Subdivisional Lines
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

T 25 S R 4 W

S 21	S 22
S 28	S 27

1957

from which the remains of the original bearing trees

A fir stump, 35 ins. diam., bears N. 55 1/2° E.,
34 lks. dist., no marks visible on burned
blaze.

A cedar stump, 22 ins. diam., bears S. 13° E.,
39 lks. dist., no marks visible on burned
blaze.

A cedar, 18 ins. diam., bears S. 31 1/2° W.,
20 lks. dist., with scribe marks R4 visible
on opened blaze.

A cedar stump, 25 ins. diam., bears N. 41° W.,
15 lks. dist., with healed blaze.
(Record, N. 45° W.)

and the remains of a bearing tree mkd. by Vernon Tracy,
Deputy County Surveyor, in 1965

A fir stump, 22 ins. diam., bears S. 13 1/2° E.,
143 lks. dist., no marks visible.
(Record, S. 15° E.)

and new bearing trees

An oak, 6 ins. diam., bears N. 67° E.,
177 lks. dist., mkd. T25S R4W S22 BT.

A yew, 10 ins. diam., bears S. 65 1/2° E.,
173 lks. dist., mkd. T25S R4W S27 BT.

An oak, 7 ins. diam., N. 7° W., 228 lks.
dist., mkd. T25S R4W S21 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, maple, madrone, and oak;
undergrowth, arrowwood, poison oak, salal, vine maple,
and young timber.

From the cor. of secs. 22, 23, 26, and 27.

N. 87° 22' W., bet. secs. 22 and 27.

Ascend over NE. slope, through heavy timber and dense
undergrowth.

8.75 Top of ascent; desc. over broken N. slope.

10.40 Ravine, drains N. 10° E.; asc. over NE. slope.

13.85 Top of ascent; desc. over N. slope.

14.30 Ravine, drains N. 45° E.; asc. over NE. slope.

26.65 Spur, slopes N. 15° E.; desc. over W. slope.

31.45 Dirt road, 20 lks. wide, bears N. 45° W. and S. 45° E.