

County Surveyor's Record, Douglas County, Oregon

17777

Dependent Resurvey, Portion of the Subdivisional Lines
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
20.14	<p>A madrone, 13 ins. diam., bears N. 1° E., 136 lks. dist., with healed double blaze.</p> <p>A madrone 16 ins. diam., bears S. 85 1/4° E., 148 lks. dist., with healed blaze.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 89° 22' W., beginning new measurement.</p> <p>Descend over broken SW. slope.</p> <p>The cor. of secs. 21, 22, 27, and 28.</p> <p>Land, mountainous Soil, rocky clay. Timber, fir, cedar, oak, madrone, hemlock, yew, and maple; undergrowth, arrowwood, vine maple, fer, poison oak, salal, and young timber.</p>
	<p>Subdivision of Section 23, T. 25 S., R. 4 W., Willamette Meridian, Oregon</p>
1.75	<p>From the 1/4 sec. cor. of secs. 23 and 26.</p> <p>N. 2° 57' E., on the N. and S. center line of sec. 23.</p> <p>Descend over N. slope, changing to NE. slope, through heavy timber and dense undergrowth.</p> <p>Gravelled road, 15 lks. wide, bears N. 65° E. and S. 55° W.</p>
10.95	Ravine, drains N. 45° E.; asc. over SE. slope.
17.90	Spur, slopes N. 50° E.; desc. broken N. slope, changing to NE. slope.
19.58	<p>Point for the center S 1/16 sec. cor. of sec. 23.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum, cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p style="margin: 0;">S 1/16 S 23</p> <p style="margin: 0;">C</p> <p style="margin: 0;">1983</p> </div> <p>from which</p> <p>A fir, 14 ins. diam., bears N. 34 1/2° E., 54 1/2 lks. dist., mkd. CS 1/16 S23 BT.</p> <p>A cedar, 23 ins. diam., bears S. 29 1/2° E., 11 1/2 lks. dist., mkd. CS 1/16 S23 BT.</p> <p>Descend over NE. slope.</p>
24.75	Ravine, drains N. 75° E.; asc. over broken SE. slope.
37.10	Spur, slopes N. 60° E.; desc. over NE. slope.
39.16	Point for the center 1/4 sec. cor. of sec. 23, at inter- section with the E. and W. center line.