

# County Surveyor's Record, Douglas County, Oregon

17781

Subdivision of Section 27,  
T. 25 S., R. 4 W., Willamette Meridian, Oregon

**CHAINS**

37.44

Point for the center 1/4 sec. cor. of sec. 27, at intersection with the E. and W. center line.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, with aluminum cap mkd.

T 25 S R 4 W  
C 1/4  
S 27

1983

from which

A grand fir, 8 ins. diam., bears S. 68 1/4° E.,  
48 lks. dist., mkd. C 1/4 S27 BT.

A fir, 12 ins. diam., bears N. 28° W.,  
2 lks. dist., mkd. C 1/4 S27 BT.

Descend over NW. slope.

57.69

Point for the center N 1/16 sec. cor. of sec. 27.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

C  
N 1/6 | S 27  
C

1983

from which

A fir, 12 ins. diam., bears S. 51° E.,  
17 lks. dist., mkd. CN 1/16 S27 BT.

A fir, 13 ins. diam., bears N. 74 1/2° W.,  
14 lks. dist., mkd. CN 1/16 S27 BT.

Descend over NW. slope.

60.89

Creek, 5 lks. wide, course N. 75° W.; asc. over SW. slope.

77.94

The 1/4 sec. cor. of secs. 22 and 27.

From the 1/4 sec. cor. of secs. 26 and 27.

N. 88° 49' W., on the E. and W. center line of sec. 27.

Ascend broken SE. slope, through scattering timber and dense undergrowth.

21.20

Gravel road, 15 lks. wide, bears N. 20° E. and S. 20° W.

26.55

Spur, slopes S. 20° W.; desc. over NW. slope.

38.27

The center 1/4 sec. cor. of sec. 27.

Descend along broken NW. slope.

58.48

Point for the center W 1/16 sec. cor. of sec. 27.