

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 27,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

17782

CHAINS	
75.20	<p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>W 1/16</p> <p>C-----C</p> <p>S 27</p> <p>1983</p> </div> <p>from which</p> <p style="margin-left: 40px;">A cedar, 31 ins. diam., bears N. 41 1/4° E., 30 lks. dist., mkd. CW 1/16 S27 BT.</p> <p style="margin-left: 40px;">A fir, 5 ins. diam., bears S. 38 1/2° W., 27 lks. dist., mkd. CW 1/16 S27 BT.</p> <p>Descend over NW. slope.</p>
78.69	<p>Creek, 3 lks. wide, course N. 10° W.; asc. over E. slope.</p> <p>The 1/4 sec. cor. of secs. 27 and 28.</p>
18.80	<p>From the W 1/16 sec. cor. of secs. 27 and 34.</p> <p>N. 0° 09' W., on the N. and S. center line of the SW 1/4 of sec. 27.</p> <p>Ascend over SE. slope, through scattering timber and dense undergrowth.</p>
19.38	<p>Gravel road, 15 lks. wide, bears N. 70° E. and S. 75° W.</p> <p>Point for the SW 1/16 sec. cor. of sec. 27, at intersection with the E. and W. center line of the SW 1/4.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>SW 1/16</p> <p>S 27</p> <p>1983</p> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 12 ins. diam., bears N. 46 3/4° E., 48 lks. dist., mkd. SW 1/16 S27 BT.</p> <p style="margin-left: 40px;">A cedar, 6 ins. diam., bears N. 73 3/4° W., 89 lks. dist., mkd. SW 1/16 S27 BT.</p> <p>Ascend SE. slope.</p>
22.30	<p>Ridge, bears N. 60° E. and S. 75° W.; desc. over NW. slope.</p>
38.79	<p>The center W 1/16 sec. cor. of sec. 27.</p>
	<p>From the center S 1/16 sec. cor. of sec. 27.</p> <p>S. 89° 15' W., on the E. and W. center line of the SW 1/4 of sec. 27.</p> <p>Ascend along broken SE. slope, through scattering timber and dense undergrowth.</p>