

County Surveyor's Record, Douglas County, Oregon

17783

Subdivision of Section 27,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
19.45	Gravel road, 15 lks. wide, bears N. 75° E. and S. 70° W.
20.23	The SW 1/16 sec. cor. of sec. 27. Ascend over SE. slope.
27.45	Ridge, bears N. 75° E. and S. 70° W.; desc. over NW. slope.
40.48	The S 1/16 sec. cor. of secs. 27 and 28.
13.70	From the center W 1/16 sec. cor. of sec. 27. N. 0° 04' W., on the N. and S. center line of the NW 1/4 of sec. 27. Descend over broken NE. slope. Creek, 3 lks. wide, course N. 30° W.; asc. over SW. slope.
18.55	Spur, slopes S. 85° W.; desc. over NW. slope.
20.16	Point for the NW 1/16 sec. cor. of sec. 27, at intersection with the E. and W. center line of the NW 1/4. Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd. NW 1/16 S 27 1983 from which A fir, 11 ins. diam., bears S. 76° E., 21 lks. dist., mkd. NW 1/16 S27 BT. A grand fir, 9 ins. diam., bears S. 88° W., 20 lks. dist., mkd. NW 1/16 S27 BT. Descend over NW. slope.
30.60	Creek, 5 lks. wide, course S. 50° W.; asc. over S. slope.
31.30	Dirt road, 15 lks. wide, bears E. and W.
40.32	The W 1/16 sec. cor. of secs. 22 and 27.
0.75	From the center N 1/16 sec. cor. of sec. 27. N. 89° 02' W., on the E. and W. center line of the NW 1/4 of sec. 27. Ascend over NW. slope, through heavy timber and dense undergrowth. Spur, slopes N. 15° E.; desc. along broken NW. slope.
16.00	Spur, slopes N. 35° E.; desc. along broken NW. slope.
20.16	The NW 1/16 sec. cor. of sec. 27. Descend over NW. slope.