

County Surveyor's Record, Douglas County, Oregon

17809

Subdivision of Section 33,
T. 24 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

N. 0° 09' E., on the N. and S. center line of sec. 33.

Descend over NE. slope, through scattering timber and moderate undergrowth.

1.90 Ravine, 10 lks. wide, drains N. 55° W.; asc. along broken W. slope.

25.70 Dirt road, 15 lks. wide, bears N. 80° E. and N. 85° W., in curve.

29.60 Spur, slopes S. 85° W.; desc. over broken NW. slope.

39.91 Point for the center 1/4 sec. cor. of sec. 33, at intersection with the E. and W. center line.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24 S R 4 W
 C 1/4
 S 33

1983

from which

A fir, 10 ins. diam., bears N. 43 1/2° E., 21 lks. dist., mkd. C 1/4 S33 BT.

A fir, 12 ins. diam., bears S. 46° W., 24 lks. dist., mkd. C 1/4 S33 BT.

Descend over broken NW. slope.

68.60 Driver Valley Road, asphalt surface, 30 lks. wide, bears N. 45° E. and S. 45° W.

70.10 Creek, 8 lks. wide, course S. 45° W.; asc. slightly over nearly level land.

80.19 The 1/4 sec. cor. of secs. 28 and 33, perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1963, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE
T 24 S
1/4 S 28
 S 33
 R 4 W

1963

from which an original bearing tree

A white oak, 33ins. diam., bears S. 54° E., 668 lks. dist., with healed blaze.

and bearing trees mkd. by Godfrey

An ash, 33 ins. diam., bears S. 62° E., 17 1/2 lks. dist., with healed blaze.

A white oak, 14 ins. diam., bears N. 52° W., 334 lks. dist., with healed blaze.