

County Surveyor's Record, Douglas County, Oregon

17811

Subdivision of Section 33,
T. 24 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

from which the remains of an original bearing tree

A white oak, 38 ins. diam., bears N. 25° E.,
240 lks. dist., with scribe marks 1/4 S visible
on opened blaze.

and bearing trees mkd. by Milo E. Godfrey, Deputy County
Surveyor, in 1963

A white oak, 10 ins. diam., bears N. 75° E.,
223 lks. dist., with healed blaze.

An ash, 23 ins. diam., bears S. 24° W.,
414 lks. dist., with healed blaze.

GENERAL DESCRIPTION

The land included in the foregoing survey is located in Douglas County about eight miles northeasterly from the town of Sutherlin, Oregon. Access is by way of a paved county road which leads from Sutherlin to Fair Oaks, Oregon, and Driver Valley Road which branches from it.

The area is drained by several small creeks draining into Long Creek and Calapooya Creek which flows southwesterly and northwesterly, respectively. Elevations range from about 700 feet above sea level near the 1/4 section corner of sections 28 and 33, to about 1,060 feet above sea level near the 1/4 section corner of sections 33 and 34.

The soil is composed of rocky clay loam, and is used for agricultural purposes in the lowlands, and recreation and timber in the upper regions. Timber consists of fir, hemlock, cedar, maple, oak, chinquapin, alder, and ash. The undergrowth consists of salal, vine maple, poison oak, arrowwood, fern, and Oregon grape.

No mineral deposits were noted along the lines surveyed.

The average of considerable number of readings throughout the area gives a value of 19° 30' E. for the mean magnetic declination. There is a range of up to 1° in local attraction.