

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 25,
T. 20 S., R. 10 W., Willamette Meridian, Oregon

17829

CHAINS	
55.15	Spur, slopes S. 55° W.; desc. over NW. slope, changing to broken SW. slope.
58.25	Same gravelled road, 20 lks. wide, bears N. 10° W. and S. 10° E. Also leave logged area, edge bears same; enter timber.
72.45	Ravine, drains S. 5° W.; asc. over SE. slope.
75.05	Spur, slopes S. 50° W.; desc. over SW. slope.
75.30	The 1/4 sec. cor. of secs. 25 and 26, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.
	$\begin{array}{c} 1/4 \\ \\ \text{S } 26 \quad \quad \text{S } 25 \\ \\ 1951 \end{array}$
	from which bearing trees mkd. by Tillman
	A fir, 13 ins. diam., bears N. 36° E., 15 lks. dist., with healed blaze.
	A fir, 38 ins. diam., bears S. 55 1/2° W., 39 lks. dist., with healed blaze.
	From the E 1/16 sec. cor. of secs. 25 and 36.
	N. 0° 42' W., on the N. and S. center line of the SE 1/4 of sec. 25.
	Ascend over SW. slope, through heavy timber and dense undergrowth.
4.95	Spur, slopes S. 40° W.; desc. over broken NW. slope.
17.25	Creek, 4 lks. wide, course S. 15° W.; asc. over SE. slope.
19.38	Point for the SE 1/16 sec. cor. of sec. 25, at intersection with the E. and W. center line of the SE 1/4.
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} \text{SE } 1/16 \quad \text{S } 25 \\ \\ 1983 \end{array}$
	from which
	A fir, 22 ins. diam., bears N. 84 3/4° E., 187 lks. dist., mkd. SE 1/16 S25 BT.
	A fir, 24 ins. diam., bears S. 46 3/4° W., 53 lks. dist., mkd. SE 1/16 S25 BT.
	Ascend over broken SE. slope.
37.45	Saddle in spur, bears N. 55° E. and S. 60° W.; desc. over NW. slope.
38.76	The center E 1/16 sec. cor. of sec. 25.