

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 34,
T. 20 S., R. 10 W., Willamette Meridian, Oregon

17833

CHAINS	
51.90	Barbed wire fence, 4 strands, extends N. 15° W. and S. 15° E.; also enter field, edge bears same.
62.10	Right bank of Smith River, bears N. 10° W. and S. 10° E.; course N. 10° W.; thence across river.
63.40	Left bank of Smith River, bears N. 10° W. and S. 10° E.; asc. over precipitous E. slope, through heavy timber and dense undergrowth.
69.15	Saddle in spur, bears N. and S.; desc. over broken W. slope.
77.49	The 1/4 sec. cor. of secs. 33 and 34, monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.
	$ \begin{array}{c} 1/4 \\ \\ S\ 33 \quad \quad S\ 34 \\ \\ 1951 \end{array} $
	from which the remains of the bearing trees mkd. by Tillman
	A double top maple, 38 ins. diam., bears S. 35 3/4° E., 62 lks. dist., with scribe marks 1/4 S34 BT visible on open blaze.
	A root hole, bears S. 47 3/4° W., 35 lks. dist., with a down alder alongside, 28 ins. diam., no marks visible.
	and a new bearing tree
	A double top maple, 40 ins. diam., bears N. 72° W., 49 lks. dist., mkd. 1/4 S33 BT.
	From the center E 1/16 sec. cor. of sec. 34.
	N. 0° 26' E., on the N. and S. center line of the NE 1/4 of sec. 34.
	Ascend over SE. slope, through heavy timber and dense undergrowth.
1.60	Spur, slopes E.; desc. over NE. slope.
3.45	Ravine, drains E.; asc. over broken SE. slope.
18.00	Ravine, drains S. 25° E.; asc. over precipitous SW. slope, changing to S. slope.
20.05	True point for the NE 1/16 sec. cor. of sec. 34, at intersection with E. and W. center line of the NE 1/4, is located on near vertical rock face, sloping S., where it is impractical to establish a permanent monument.
20.15	Point selected for the witness cor. to the NE 1/16 sec. cor. of sec. 34.
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, to solid rock, and in a mound of stone, 2 ft. base, to top, with brass cap mkd.