

County Surveyor's Record, Douglas County, Oregon

17846

Dependent Resurvey of a Portion of the South Boundary,
T. 30 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

(Restoring the survey by William M. Bushey, in 1893)

Beginning at the cor. of secs. 35 and 36 only, perpetuated and recorded by John H. Markham, Jr., Registered Engineer, No. 2880, in 1959, and further perpetuated and recorded by John M. Powell, Deputy County Surveyor, in 1965, monumented with an iron post, 1½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 30 S R 3 W
S 35 | S 36
S 2
T 31 S R 3 W

1965

from which the remaining original bearing tree

A cedar, 23 ins. diam., bears N. 57¼° E.,
17½ lks. dist., with healed blaze.

and remains of bearing trees mkd. by Markham

A cedar, 14 ins. diam., bears N. 7° E.,
67 lks. dist., with scribe marks S36 BT
visible on partially healed blaze.

A madrone, 19 ins. diam., bears S. 80° E.,
35 lks. dist., with healed blaze.

A madrone stump, 13 ins. diam., bears N. 75° W.,
67 lks. dist., no marks visible.

and the remains of a bearing tree mkd. by Powell

A sawed fir stump, 24 ins. diam., bears
N. 65½° W., 32 lks. dist., with healed blaze.

and a new bearing tree

A cedar, 9 ins. diam., bears N. 32° W.,
208 lks, dist., mkd. T30S R3W S35 BT.

N. 89° 53'W., on the S. bdy. of sec. 35, marking and
blazing the true line.

Descend over broken SW. slope changing to NW. slope,
through heavy timber and dense undergrowth.

2.40 Gravelled road, 20 lks. wide, bears N. 10° E. and
S. 10° W.

25.75 Creek, 5 lks. wide, course N. 15° E.; asc. over broken
NE. slope.

35.20 Gravelled road, 20 lks. wide, bears N. 10° E. and
S. 5° W.

40.97 The ¼ sec. cor. of sec. 35 only, perpetuated and
recorded by Richard L. Templin, Jr., Registered
Engineer No. 3024, in 1953, and further perpetuated and
recorded by John M. Powell, Deputy County Surveyor, in
1965, Monumented with the remains of the original