

# County Surveyor's Record, Douglas County, Oregon

**17854** Dependent Resurvey, Portion of the Subdivisional Lines,  
T. 30 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears S. 76 1/2° E., 54 lks. dist.,  
with down fir alongside, 30 ins. diam., no  
marks visible.

A fir stump, size indeterminate, bears  
N. 75 1/4° W., 64 lks. dist., no marks visible.

and a bearing tree mkd. by Templin

A fir, 16 ins. diam., bears S. 36 1/2° W.,  
15 lks. dist., with healed blaze.

and a bearing tree mkd. by Byron

A cedar, 22 ins. diam., bears S. 87 3/4° E.,  
28 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 30 S    R 3 W  
          1/4  
          |  
          S 34 | S 35  
          |  
          1983

Reset iron pipe alongside iron post.

N. 1° 23' W., beginning new measurement.

Ascend over broken SW. slope.

8.80

Spur, slopes NW.; desc. over broken NE. slope, also  
gravelled road, 20 lks. wide, bears NW. and SE.

20.115

The N 1/16 sec. cor. of secs. 34 and 35, established  
and recorded by Richard L. Templin, Jr., Registered  
Logging Engineer, No. 3024, in 1954, and is accepted as  
the corner, monumented with an iron pipe, 3/4 in. diam.,  
firmly set, projecting 6 ins. above ground, from which  
the remains of bearing trees mkd. by Templin

A root hole, bears N. 79 1/2° E., 40 lks.  
dist., with down grand fir alongside, size  
indeterminate, no marks visible.

A cedar root crown, bears S. 80 1/2° W., 42 lks.  
dist., with down cedar alongside, 24 ins.  
diam., with scribe marks 1/16 4 BT visible  
on decayed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins.  
in the ground, with brass cap mkd.

N 1/16  
          |  
          S 34 | S 35  
          |  
          1983

from which new bearing trees