

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 30 S., R. 3 W., Willamette Meridian, Oregon

17861

CHAINS

and a bearing tree mkd. by Wenderoth

A cedar, 30 ins. diam., bears S. 31° E.,
64 lks. dist., with healed blaze.

and a bearing tree mkd. by Byron

A fir, 28 ins. diam., bears S. 43° W.,
122 lks. dist., with healed blaze.

and bearing trees mkd. by Monrean

A fir, 46 ins. diam., bears N. 46° E.,
72 lks. dist., with scribe marks T30S
R3W S17 CS BT visible on open double
blaze.

A fir, 12 ins. diam., bears N. 59 1/2° W.,
78 lks. dist., with healed blaze.

The corner is located 60 lks. west of and 15 ft. higher
than a creek, 5 lks. wide, course S. 25° E.

Land, mountainous.

Soil, rocky clay.

Timber, cedar, maple, fir, hemlock, oak, madrone,
alder, yew, and chinquapin; undergrowth, poison oak,
vine maple, arrowwood, hazel, Oregon grape, huckle-
berry, manzanita, salal, ferns, blackberry, and young
timber.

S. 85° 50' W., bet. secs. 18 and 19.

Ascend over NE. slope, changing to SE. slope, through
heavy timber and dense undergrowth.

10.65

Spur, slopes S. 30° W.; desc. over SW. slope.

16.20

Creek, 1 lk. wide, course S. 10° E.; asc. over
SE. slope.

19.68

The E 1/16 sec. cor. of secs. 18 and 19, established
and recorded by George J. Wenderoth, Registered Land
Surveyor, No. 5, in 1950-51, and is accepted as the
corner, monumented with an angle iron, 1 1/4 x 1/4 ins.,
firmly set, projecting 8 ins. above ground; from which
the remains of bearing trees mkd. by Wenderoth

A madrone snag, 18 ins. diam., bears
N. 47° E., 30 1/2 lks. dist., with scribe
marks T 6 S C BT visible on decayed
blaze.

A madrone, 18 ins. diam., bears N. 52° W.,
33 lks. dist., with fragmentary scribe
marks visible on decayed blaze.

At the corner point

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam.,
22 ins. in the ground, with aluminum cap mkd.

E 1/16 $\frac{S\ 18}{S\ 19}$

1983