

# County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 19,  
T. 30 S., R. 3 W., Willamette Meridian, Oregon

17867

CHAINS	
	<p>From this point, a corner established and recorded by George J. Wenderoth, Registered Land Surveyor, No. 5, in 1950-51, bears N. 77°04' E., 0.188 chs. dist., monumented with an angle iron, 1 x ¼ ins., firmly set, projecting 12 ins. above ground, from which bearing trees mkd. by Wenderoth</p> <p style="padding-left: 40px;">A fir, 30 ins. diam., bears S. 65½° E., 35 lks. dist., with healed double blaze.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S. 23° W., 25 lks. dist., with healed double blaze.</p> <p>Ascend over broken SE. slope.</p>
34.80	Spur, slopes S. 30° E.; asc. over SE. slope.
39.49	The E 1/16 sec. cor. of secs. 18 and 19.
	<p>From the N 1/16 sec. cor. of secs. 19 and 20.</p> <p>S. 86° 22' W., on the E. and W. center line of the NE 1/4 of sec. 19.</p> <p>Descend over NW. slope, through heavy timber and dense undergrowth.</p>
15.05	Lavadoure Creek, 10 lks. wide, course S. 5° W.; asc. over broken SE. slope.
19.74	The NE 1/16 sec. cor. of sec. 19.
	Ascend over broken SE. slope.
39.60	The center N 1/16 sec. cor. of sec. 19.
	<p>From the W 1/16 sec. cor. of secs. 19 and 30.</p> <p>N. 0° 22' W., on the N. and S. center line of the SW¼ of sec. 19.</p> <p>Descend over broken NW. slope, through heavy timber and dense undergrowth.</p>
8.50	Ravine, drains SW.; asc. over SW. slope.
18.40	Spur, slopes S. 50° W.; desc. over broken NW. slope.
19.565	Point for the SW 1/16 sec. cor. of sec. 19, at intersection with the E. and W. center line of the SW 1/4.
	<p>Set an aluminum post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with aluminum, cap mkd.</p> <p style="text-align: center;">SW 1/16 S 19 1983</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 4 ins. diam., bears N. 21° E., 9 lks. dist., mkd. X BT.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S. 31° W., 32 lks. dist., mkd. SW 1/16 S19 BT.</p>