

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 35,
T. 30 S., R. 3 W., Willamette Meridian, Oregon

17869

CHAINS	
50.67	<p>The center N 1/16 sec. cor. of sec. 35, established and recorded by Donald L. McConnell, Registered Land Surveyor, in 1979, and is accepted as the corner, monumented with an iron rod, 5/8 in. diam., firmly set, projecting 2 ins. above ground.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over iron rod, with brass cap mkd.</p> <div style="text-align: center;"> <p>C N 1/16 S 35 C 1983</p> </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 11 ins. diam., bears N. 53½° E., 56 lks. dist., mkd. CN 1/16 S35 BT.</p> <p style="padding-left: 40px;">A fir, 25 ins. diam., bears S. 29° W., 33 lks. dist., mkd. CN 1/16 S35 BT.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 0° 01' E., beginning new measurement.</p> <p>Descend over NW. slope.</p>
7.00	Gravelled road, 15 lks. wide, bears N. 15° E. and S. 35° W.
19.71	The 1/4 sec. cor. of secs. 26 and 35.
	<p>From the 1/4 sec. cor. of secs. 35 and 36.</p> <p>S. 89° 01' W., on the E. and W. centre line of sec. 35.</p> <p>Ascend over SE. slope, through heavy timber and dense undergrowth.</p>
2.50	Top of ascent, slopes S. 10° E.; desc. over broken SW. slope.
13.10	Gravelled road, 20 lks. wide, bears N. 40° E. and S. 20° E.
36.50	Creek, 10 lks. wide, course N. 35° W.; asc. over NE. slope.
40.62	The center 1/4 sec. cor. of sec. 35.
	Ascend over NE. slope.
54.50	Spur, slopes N. 20° W.; desc. over broken NW. slope.
73.15	Spur, slopes N. 30° W.; desc. over broken NW. slope, also gravelled road, 25 lks. wide, bears N. 30° W. and S. 30° E.
81.03	The 1/4 sec. cor. of secs. 34 and 35.
	<p>From the center N 1/16 sec. cor. of sec. 35.</p> <p>S. 89° 36' W., on the E. and W. center line of the NW 1/4 of Sec. 35.</p>