

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 5 W., Willamette Meridian, Oregon

17875

CHAINS

3.85

Top of ascent, slopes NW.; desc. over NW. slope, changing to N. slope.

17.20

Ravine, drains N. 60° E.; asc. over SE. slope.

19.76

The cor. of secs. 13, 14, 23, and 24, perpetuated and recorded by George J. Wenderoth, Registered Land Surveyor, No. 5, in 1953, from original evidence no longer in existence. Mr. Donald W. Brady, a resident of the area for many years, furnished a signed statement, attached to and made a portion of these field notes, attesting to the corner position. The corner is monumented with an iron pipe, ½ in. diam., firmly set, projecting 4 ins. above ground, from which bearing trees mkd. by Wenderoth:

A cedar, 15 ins. diam., bears N. 20° E., 44 lks. dist., with healed blaze.

A fir, 22 ins. diam., bears S. 60½° E., 88 lks. dist., with healed blaze.

A cedar, 19 ins. diam., bears S. 67° W., 40½ lks. dist., with healed blaze.

A cedar, 21 ins. diam., bears N. 37½° W., 47 lks. dist., with healed blaze.

and a bearing tree mkd. by person(s) unknown

The east fork of a twin fir, 24 ins. diam., bears S. 31½° W., 22 lks. dist., with healed blaze. at breast height.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over iron pipe, with brass cap mkd.

T 32 S R 5 W	
S 14	S 13
S 23	S 24

1983

Land, mountainous.

Soil, rocky clay.

Timber, pine, fir, cedar, oak, maple, dogwood, and madrone; undergrowth, poison oak, ceanothus, Oregon grape, manzanita, salal, grass, and weeds.

From the cor. of secs. 23, 24, 25, and 26.

N. 89° 48' W., bet. secs. 23 and 26.

Descend over SW. slope, through dense timber and dense undergrowth.

0.55

Ravine, drains S. 20° W.; asc. over broken SE. slope, changing to S. slope.

19.10

Top of ascent, slopes S.; desc. over broken W. slope.

38.55

Ravine, drains S. 45° W.; asc. over SW. slope, changing to S. slope.