

# County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey,  
 Portion of the Subdivisional Lines,  
 T. 22 S., R.9 W., Willamette Meridian, Oregon

17909

**CHAINS**

A fir snag, 45 ins. diam., bears N. 37° E.  
 29 lks. dist., no marks visible on decayed  
 remains. (Record, N. 42° E.)

A root hole, bears S. 55° E., 52 lks. dist.,  
 with a downed, decayed fir, size indeterminate,  
 alongside, no marks visible.

A fir stump, 35 in. diam., bears N. 41° W.,  
 52 lks. dist., no marks visible on decayed  
 remains. (Record, 88 lks. dist.)

From this point, the cor. of secs. 22, 23, 26, and 27  
 erroneously reestablished by Wofford, Rogers, and  
 Chatters, in 1973-79, bears N. 2° 33' W., 1.034 chs.  
 dist., monumented with an iron post, 2½ ins. diam.,  
 firmly set, projecting 6 ins. above ground, with brass  
 cap mkd. and witnessed as described in the official  
 record.

Remove the iron post, destroy the marks on the bearing  
 trees, and at the true corner point

Reset the iron post, 28 ins. long, 2½ ins. diam.,  
 25 ins. in the ground, with brass cap mkd.

T 22 S R 9 W	
S 22	S 23
S 27	S 26

1983

from which new bearing trees

A fir, 10 ins. diam., bears N. 59° E.,  
 51 lks. dist., mkd. T22S R9W S 23 BT.

A fir, 13 in. diam., bears S. 87° E.,  
 50 lks. dist., mkd. T22S R9W S26 BT.

A fir, 18 ins. diam., bears S. 76½° W.,  
 86 lks. dist., mkd. T22S R9W S27 BT.

A fir, 20 ins. diam., bears N. 87° W.,  
 113 lks. dist., mkd. T22S R9W S22 BT.

Deposit the original stone alongside the iron post.

Corner is located in a ravine, drains W.

Land, mountainous.

Soil, Rocky, clay loam.

Timber, fir, hemlock, cedar, oak, maple, and alder;  
 undergrowth, fern, fine maple, salal, Oregon grape,  
 poison oak, blackberry, thimbleberry, and rhododendron.

From the ¼ sec. cor. of secs. 23 and 26, monumented  
 with an iron post, 2½ ins. diam., firmly set,  
 projecting 6 ins. above ground, with brass cap mkd.

T 22 S R 9 W	
S 23	
¼	S 26

1974