

# County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey,  
Portion of the Subdivisional Lines,  
T. 22 S., R. 9 W., Willamette Meridian, Oregon

17913

**CHAINS**

Land, mountainous.  
Soil, rocky clay.  
Timber, fir, hemlock, cedar, oar, maple, and alder;  
undergrowth, fern vine maple, salal, Oregon grape,  
poison oak, blackberry, thimbleberry, and rhododendron.

From the cor. of secs. 27 and 35 only, on the W. bdy.  
of sec. 26.

N. 89° 13' W., bet. secs. 27 and 35.

Ascend along S. slope, through heavy timber and dense  
undergrowth.

10.03

The cor. of secs. 34 and 35, monumented with an iron  
post, 2½ ins. diam., firmly set, projecting 6 ins.  
above ground, with brass cap mkd.

T 22 S	R 9 W
S 27	
S 34	S 35
1974	

from which the remaining original bearing tree

A cedar, 50 ins. diam., bears S. 4° E.,  
116 lks. dist., with healed blaze.

and bearing tree of no known record

A fir, 36 ins. diam., bears S. 50° W.,  
9 lks. dist., with healed blaze.

and a bearing tree mkd. by Wofford, Rogers, and Chatters

A fir, 16 ins. diam., bears S. 65° E.,  
67 lks. dist., with healed blaze.

S. 89° 28' W., beginning new measurement, bet.  
secs. 27 and 34.

Ascend along broken S. slope.

3.30

Creek, 1 lk. wide, course S. 70° E.; asc. over  
NE. slope.

5.40

Creek, 1 lk. wide, course N. 65° E.; asc. over  
NE Slope.

19.095

Point for the E 1/16 sec. cor. of sec. 34 only.

From this point the E 1/16 sec. cor. of sec. 34 only,  
erroneously established by Wofford, Rogers, and  
Chatters, in 1973-79, bears S. 82° 43' E., 0.36 chs.  
dist., monumented with an iron post, 2½ ins. diam.,  
firmly set, projecting 4 ins. above ground, with brass  
cap mkd. and witnessed as described in the official  
record.

Remove the iron post, and at the true corner point

Reset the iron post, 28 ins. long, 2½ ins. diam.,  
24 ins. in the ground, with brass cap mkd.