

County Surveyor's Record, Douglas County, Oregon

17914

Corrective Dependent Resurvey,
 Portion of the Subdivisional Lines,
 T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

E 1/16 S 34
 1984

from which the bearing tree mkd. by Wofford, Rogers,
 and Chatters

A fir, 11 ins. diam., bears S. 70½° E.,
 24 lks. dist., mkd. E 1/16 S34 BT.

No other suitable tree available.

Continue ascent over NE. slope

23.50 Ridge, bears N. 25° W. and S. 25° E.; desc. over
 W. slope.

27.80 Dirt road, 20 lks. wide, bears N. 30° E. and
 S. 30° W.

29.55 Point for the ¼ sec. cor. of sec. 27 only,
 hereinafter described.

Continue descent over W. slope.

38.19 The ¼ sec. cor. of sec. 34 only, monumented with an
 iron post, 2 ins. diam., firmly set, projecting 14 ins.
 above ground, with brass cap mkd.

T 22 S

¼ S 34
 R 9 W
 1968

from which the remains of the original bearing trees

A fir, 37 ins. diam., bears N. 50° E.,
 51 lks. dist., with an X in bark on
 SE. and SW. faces.

A fir snag, size indeterminate, bears S. 20° E.,
 60 lks. dist., no marks visible.

and bearing trees mkd. by Vernon R. Tracy, Deputy
 County Surveyor, in 1968

A hemlock, 13 ins. diam., bears S. 9° E.,
 23 lks. dist., with healed blaze.

A fir, 8 ins. diam., bears S. 81° W.,
 23 lks. dist., with healed blaze.

N. 84° 26' W., beginning new measurement.
 Descend over broken NW. slope.

2.55 Ravine, drains NW.; desc. over broken NW. slope.

6.70 Spur, slopes N. 10° E.; desc. over NW. slope.

14.70 Rock bluff, 20 ft. high, faces S.; desc. along broken
 S. slope.