

County Surveyor's Record, Douglas County, Oregon

17916

Corrective Dependent Resurvey,
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

Reset the iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.

$$\begin{array}{r} \text{S } 22 \\ \hline \text{E } 1/16 \end{array}$$

 S 27
 1983

from which new bearing trees

A fir, 21 ins. diam., bears N. 34° E.,
39 lks. dist., mkd. E 1/16 S2 BT.

A fir, 27 ins. diam., bears S. 45½° E.,
72 lks. dist., mkd. E 1/16 S27 BT.
Corner is located at bottom of descent.

Ascend over NE. slope.

36.10 Spur, slopes N.; desc. over NW. slope.

39.74 Point for the ¼ sec. cor. of secs. 22 and 27, at
proportionate distance; there is no remaining evidence
of the original corner.

From this point the ¼ sec. cor. of secs. 22 and 27,
erroneously established by Wofford, Rogers, and
Chatters, in 1973-79, bears N. 12° 41' E., 0.519 chs.
dist., monumented with an iron post, 2½ ins. diam.,
firmly set, projecting 4 ins. above ground, with brass
cap mkd. and witnessed as described in the official
record.

Remove the iron post, and at the true corner point

Reset the iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.

$$\begin{array}{r} \text{T } 22 \text{ S} \quad \text{R } 9 \text{ W} \\ \hline \text{S } 22 \\ \frac{1}{4} \end{array}$$

 S 27
 1983

from which bearing trees mkd. by Wofford, Rogers, and
Chatters

A fir, 35 ins. diam., bears N. 17° E.,
66½ lks. dist., mkd. ¼ S22 BT

A fir, 21 ins. diam., bears S. 9° E.,
21 lks. dist., mkd. ¼ S27 BT.

Continue descent over NW. slope.

43.50 Creek, 2 lks. wide, course N. 5° W., asc. over
NE slope.

54.90 Spur, slopes N. 45° W.; desc. over NW. slope.

77.90 Creek, 4 lks. wide, course N. 25° W.; asc. over
NE. slope.

79.48 The cor. of secs. 21, 22, 27, and 28, monumented with
an iron post, 2½ ins. diam., firmly set, projecting
4 ins. above ground, with brass cap mkd.