

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey,
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon **17917**

CHAINS

T 22 S R 9 W
S 21 | S 22
S 28 | S 27
1975

from which bearing trees mkd. by Wofford, Rogers, and Chatters

A maple, 22 ins. diam., bears N. 28 1/2° E.,
66 lks. dist., with healed blaze.

A fir, 28 ins. diam., bears S. 37 3/4° E.,
60 lks. dist., with healed blaze.

A fir, 20 ins. diam., bears S. 47 1/4° W.,
15 lks. dist., with healed blaze.

A fir, 30 ins. diam., bears N. 29 1/2° W.,
83 lks. dist., with healed blaze.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, oak, maple, and alder;
undergrowth, fern, vine maple, salal, Oregon grape,
poison oak, blackberry, thimbleberry, and rhododendron.

From the 1/4 sec. cor. of secs. 27 and 28, monumented
with an iron post, 2 1/2 ins. diam., firmly set,
projecting 4 ins. above the ground, with brass cap mkd.

T 22 S R 9 W
S 28 | 1/4 | S 27
1975

from which the remains of the original bearing trees

A fir snag, size indeterminate, bears
N. 17° E., 20 lks. dist., no marks
visible.

A fir, 34 ins. diam., bears N. 45° W.,
49 lks. dist., with healed blaze.

and bearing trees mkd. by Wofford, Rogers, and Chatters

A fir, 36 ins. diam., bears S. 30° E.,
15 lks. dist., with healed blaze.

A fir, 27 ins. diam., bears West,
106 lks. dist., with healed blaze.

S. 0° 22' E., bet. secs. 27 and 28.

Ascend over N. slope, through heavy timber and dense
undergrowth.

3.60 Ridge, bears N. 70° E. and S. 70° W.; desc. over
S. slope.

5.90 Gravelled road, 20 lks. wide, bears N. 75° E. and
S. 75° W.