

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

17039

CHAINS

COUNTY SURVEYORS OFFICE

T 22 S
S 17 | S 16
S 20 | S 21
1962

from which the remains of the original bearing trees

A decayed fir stump, 60 ins. diam.,
bears S. 45° W., 36 lks. dist., with
scribe marks T22S S20 visible on bark.

A decayed fir snag, size indeterminate,
bears N. 50° W., 55 lks. dist., with
axe marks visible on bark.
(Record, N. 40° W.)

and bearing trees mkd. by Harold T. Lewis, Registered
Professional Engineer, No. 722, in 1939

A maple, 23 ins. diam., bears N. 27° E.,
50 lks. dist., no marks visible
(Record, N. 32° E.)

A hemlock, 27 ins. diam., bears S. 43° E.,
10 ½ lks. dist., with healed blaze.
(Record, S. 50° E.)

A fir, 50 ins. diam., bears N. 18° W.,
45 lks. dist., with healed blaze.
(Record, N. 14° W.)

and a bearing tree mkd. by Milo E. Godfrey, Deputy
County Surveyor, in 1962

A hemlock, 13 ins. diam., bears S. 30° W.,
65 lks. dist., with illegible scribe marks
visible on partially healed blaze.
(Record, S. 32° W.)

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, maple, and alder; under-
growth, poison oak, Oregon grape, salal, Scotch broom,
hazel, blackberry, and salmonberry.

From the cor. of secs. 15, 16, 21, and 22.

S. 88° 32' W., bet. secs. 16 and 21.

Descend over SW. slope, through dense timber and under-
growth.

- | | |
|-------|--|
| 1.30 | Dirt road, 15 lks. wide, bears N. and S. 30° E., in curve. |
| 3.60 | Ravine, drains N. 50° W.; desc. over NW. slope. |
| 6.40 | Ravine, drains S. 70° W.; desc. along S. slope. |
| 28.10 | Ravine, drains S. 35° W.; asc. over SE. slope. |
| 30.80 | Spur, slopes S. 15° W.; desc. over SW. slope. |