

County Surveyor's Record, Douglas County, Oregon

17014

Dependent Resurvey of
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

T 22 S
R 10 W | R 9 W
 | ¼ S 6
 1983

from which

A fir, 28 ins. diam., bears N. 58° E.,
34 ½ lks. dist., mkd. X BT.

A fir, 22 ins. diam., bears S. 31 ½° E.,
52 lks. dist., mkd. ¼ S6 BT.

From this point, the ¼ sec. cor. of sec. 1 only,
T. 22 S., R. 10 W., bears S. 0° 36'E., 3.86 chs.
dist., hereinbefore described.

Subdivision of Section 6,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

From the ¼ sec. cor. of secs. 6 and 7.

N. 0° 33' W., on the N. and S. center line of sec. 6,
marking and blazing the true line.

Ascend over the SE. slope, through moderate timber and
undergrowth.

3.15 Top of ascent, slopes E.; desc. over NE. slope.

9.35 Ravine, drains S. 75° E.; asc. over SE. slope.

34.00 Top of ascent, slopes E.; desc. over NE. slope.

39.80 Point for the center ¼ sec. cor. of sec. 6 at
intersection with the E. and W. center line.

Set an iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.

T 22 S R 9 W
C ¼ S 6
1982

from which

A cedar, 20 ins. diam., bears S. 32 ¼°W.,
17 lks. dist., mkd. C ¼ S6 BT.

A fir, 48 ins. diam., bears N. 76° W.,
42 lks. dist., mkd. C¼ S6 BT.

Corner is located at bottom of descent, slopes E.

Ascend along broken E. slope.

59.65 Point for the center N 1/16 sec. cor. of sec. 6.

Set an iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the gorund, with brass cap mkd.