


County Surveyor's Record, Douglas County, Oregon

17046

Subdivision of Section 6,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS



from which

A fir, 52 ins. diam., bears S. 23° W.,
74 lks. dist., mkd. X BT.

A fir, 37 ins. diam., bears N. 78 3/4° W.,
79 lks. dist., mkd. X BT.

Continue ascent over NE. slope

40.22 The center 1/4 sec. cor. of sec. 6.

Continue ascent over NE. slope.

48.10 Spur ridge, bears N. and S.; desc. over broken SW.
slope.

90.15 The 1/4 sec. cor. of sec. 6 only, on the W. bdy. of the
tp.

From the true point for the center E 1/16 sec. cor. of
sec. 6.

N. 0° 41' W., on the N. and S. center line of the
NE 1/4 of sec. 6.

Ascend over SW. slope.

7.55 Spur, slopes E., desc. over broken NE. slope.

10.90 Creek, 4 lks. wide, course S. 60° E.; asc. over
broken SE. slope.

12.60 Spur, slopes E.; desc. over NE. slope.

19.80 Creek, 2 lks. wide, course N. 70° E.; asc. over
SE. slope.

19.86 Point for the NE 1/16 sec. cor. of sec. 6, at inter-
section with the E. and W. center line of the NE 1/4.

Set an iron post, 28 ins. long, 2 1/2 ins. diam.,
3 ins. in the ground, to bedrock, and in a mound of
stone, 3 ft. base, to top, with brass cap mkd.

NE 1/16 S 6

1982

from which

A hemlock, 8 ins. diam., bears N. 65° E.,
34 lks. dist., mkd. NE 1/16 S6 BT.

A fir, 28 ins. diam., bears S. 4° W.,
68 lks. dist., mkd. NE 1/16 S6 BT.

Continue ascent over NE. slope.

20.90 Spur, slopes E.; desc. over broken NE. slope.