

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 6,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

17247

CHAINS

- 29.30 Creek, 20 lks. wide, course S. 40° E.; asc. over S. slope.
- 37.60 The E 1/16 sec. cor. of sec. 6 only, on the N. bdy. of the tp., monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

E 1/16	S 6
T 22 S	R 9 W
1974	

from which bearing trees mkd. by Wofford, Rogers, and Chatters

A fir, 21 ins. diam., bears S. 30° E.,
5 lks. dist., with healed blaze.

A fir, 30 ins. diam., bears S. 68° W.,
65 lks. dist., with healed blaze.

- From the N 1/16 sec. cor. of sec. 6 only, on the E. bdy. of sec. 6.
- N. 89° 45' W., on the E. and W. center line of the NE ¼ of sec. 6.
- Descend over SW. slope, through moderate timber and undergrowth.
- 1.85 Creek, 5 lks. wide, course S. 25° E.; asc. over broken E. slope.
- 20.00 Creek, 2 lks. wide, course N. 70° E.; asc. over broken E. slope.
- 20.07 The NE 1/16 sec. cor. of sec. 6.
- Continue ascent over broken E. slope.
- 40.13 The center N 1/16 sec. cor. of sec. 6.

Subdivision of Section 28
T. 22 S., R. 9 W., Willamette Meridian, Oregon

- From the ¼ sec. cor. of sec. 28 only, on the S. bdy. of sec. 28.
- N. 0° 22' W., on the N. and S. center line of sec. 28, marking and blazing the true line.
- Ascend over broken S. slope, through heavy timber and dense undergrowth.
- 12.50 Spur ridge, bears E. and W.; desc. over broken N. slope.
- 12.30 Gravelled road, 25 lks. wide, bears N. 85° E. and S. 85° W.
- 14.12 Point for the center S 1/16 sec. cor. of sec. 26. 28
per research 12/4/2023
DCSO JC