


County Surveyor's Record, Douglas County, Oregon

17048

Subdivision of Section 28,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.



Fd. BC and 2 BTs
SCRIBED 2 NEW BTs
T HOSTETTER 11/2023
M183-16

from which

A hemlock, 13 ins. diam., bears N. 78 ¾ ° E.,
83 lks. dist., mkd. CS 1/16 S28 BT.


A fir, 18 ins. diam., bears N. 20° W.,
52 lks. dist., mkd. CS 1/16 S28 BT.

Descend over broken N. slope.

33.74

Point for the center ¼ sec. cor. of sec. 28, at
intersection with the E. and W. center line.

Set an iron post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.



from which

A fir, 33 ins. diam., bears N. 47 ¼ ° E.,
49 lks. dist., mkd. C ¼ S 28 BT.

A fir, 18 ins. diam., bears S. 85 ½ ° W.,
12½ lks. dist., mkd X BT.

Descend over NW. slope.

36.10

Ravine, drains NE.; asc. over broken SE. slope.

71.70

The ¼ sec. cor. of secs. 21 and 28.

From the ¼ sec. cor. of secs. 27 and 28.

N. 89° 54' W., on the E. and W. center line of
Sec. 28.

Descend over broken NW. slope, through heavy timber and
dense undergrowth.

1.85

Ravine, drains N. 15° E.; asc. over broken E. slope.

12.35

Spur, slopes N.; desc. over broken W. slope.

23.00

Ravine, drains NW.; desc. along broken N. slope.

41.29

The center ¼ sec. cor. of sec. 28.

Descend along broken N. slope.

42.45

Ravine, drains N. 30° E.; asc. over broken E. slope.