

# County Surveyor's Record, Douglas County, Oregon

**17954** Dependent Resurvey, Portion of the Subdivisional Lines,  
T. 27 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

T 27 S R 3 W  
S 11 | S 12  
S 14 | S 13

1958

from which the remains of the original bearing trees

A fir stump, 54 ins. diam., bears N.  $45\frac{1}{2}^{\circ}$  E.,  
109 lks. dist., no marks visible.

A madrone, 53 ins. diam., bears S.  $10^{\circ}$  W.,  
32 lks. dist., with opened blaze, no marks  
visible.

and bearing trees mkd. by Ben B. Irving, County  
Surveyor, in 1945

A fir, 40 ins. diam., bears S.  $72\frac{1}{2}^{\circ}$  E.,  
136 lks. dist., with healed double blaze.

A fir, 16 ins. diam., bears S.  $10\frac{1}{2}^{\circ}$  W.,  
19 lks. dist., with healed double blaze.

A fir, 23 ins. diam., bears N.  $54\frac{3}{4}^{\circ}$  W.,  
24 lks. dist., with healed double blaze.

and bearing trees mkd. by Corbin

A fir, 9 ins. diam., bears N.  $61\frac{1}{2}^{\circ}$  E.,  
46 lks. dist., with healed blaze.

A fir, 8 ins. diam., bears S.  $40\frac{1}{4}^{\circ}$  E.,  
65 lks. dist., with healed blaze.

A fir, 9 ins. diam., bears S.  $64^{\circ}$  W.,  
6 lks. dist., with healed blaze.

A fir, 16 ins. diam., bears N.  $11\frac{1}{4}^{\circ}$  W.,  
13 lks. dist., with healed blaze.

N.  $0^{\circ} 41'$  E., bet. secs. 11 and 12, marking and blazing  
the true line.

Ascend over SW. slope, through scattering timber and  
dense undergrowth.

7.05

Spur, slopes S.  $45^{\circ}$  E.; desc. over NE. slope.

40.20

The  $\frac{1}{4}$  sec. cor. of secs. 11 and 12, monumented with an  
iron post,  $2\frac{1}{2}$  ins. diam., firmly set, projecting 4 ins.  
above ground, with brass cap mkd.

FD. OK 3/97 by DeGroot  
1997-0113

T 27 S R 3 W  
 $\frac{1}{4}$   
S 11 | S 12  
1958

from which the remaining original bearing tree