

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, 17957  
T. 27 S. R. 3 W., Willamette Meridian, Oregon

**CHAINS**

A cedar, 25 ins. diam., bears S. 58° W.,  
29 lks. dist., with healed double blaze.  
(Record, S. 53° W.)

and a bearing tree mkd. by Corbin

A fir, 22 ins. diam., bears S. 13° E.,  
78 lks. dist., with healed blaze.

and a new bearing tree

A cedar, 19 ins. diam., bears N. 43° W.,  
117 lks. dist., mkd. T27S R3W S10 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, oak, madrone, and maple;  
undergrowth, hazel, vine maple, dogwood, poison oak,  
and salal.

From the cor. of secs. 2, 3, 10, and 11, monumented  
with an iron post, 2½ ins. diam., firmly set, project-  
ing 6 ins. above ground, with brass cap mkd.

T 27 S	R 3 W
S 3	S 2
S 10	S 11

1958

FD. OK BY HEIMBURGER  
3/94 M 118-54  
FD. OK BY HEIMBURGER  
10/95 M 122-68

from which the remains of the original bearing trees

A fir stump, 30 ins. diam., bears S. 65° E.,  
19 lks. dist., with faint scribe marks  
visible on bark.

A fir stump, 27 ins. diam., bears S. 75° W.,  
17 lks. dist., with scribe marks T27S R3W  
visible on bark blaze.

A fir, 17 ins. diam., bears N. 35° W.,  
17 lks. dist., with scribe marks T27S R3W S3  
visible on bark blaze.

and a bearing tree mkd. by Ben B. Irving, County  
Surveyor, in 1945

A root hole, with down fir alongside, 24 ins.  
diam., bears N. 10° E., 37 lks. dist., no marks  
visible.

and bearing trees mkd. by Corbin

A fir, 19 ins. diam., bears N. 59° E.,  
39 lks. dist., with healed blaze.

A fir, 20 ins. diam., bears S. 31½° E.,  
53 lks. dist., with healed blaze.

A white oak, 9 ins. diam., bears S. 37° W.,  
125 lks. dist., with healed blaze.

A fir, 35 ins. diam., bears N. 12½° W.,  
55 lks. dist., with healed blaze.

N. 0° 49' W., bet. secs. 2 and 3.