

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines **17959**
T. 27 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

COUNTY SURVEYORS OFFICE

T 27 S R 3 W

$$\frac{1}{4} \frac{S 3}{S 10}$$

1969

from which the remains of the original bearing trees

A fir, 27 ins. diam., bears N. 20° E., 3 lks. dist., with healed blaze.

A rotted fir stump, 14 ins. diam., bears S. 60° W., 9 lks. dist., no marks visible.

and a bearing tree mkd. by Powell

A cedar, 17 ins. diam., bears S. 55° E., 22 lks. dist., with healed double blaze.

S. 89° 58' W., beginning new measurement.

Ascend over broken SE. slope.

20.50 Gravelled road, 15 lks. wide, bears N. 20° E. and S. 20° W.

27.50 Spur, slopes S. 35° W.; desc. over SW. slope.

41.19 The cor. of secs. 3, 4, 9, and 10, monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 27 S R 3 W

$$\frac{S 4 | S 3}{S 9 | S 10}$$

1958

from which the remains of an original bearing tree

A madrone stump, 21 ins. diam., bears N. 14° W., 64 lks. dist., with opened blaze, no marks visible.

and the remains of bearing trees mkd. by James Byron, Deputy County Surveyor, in 1957

A fir, 6 ins. diam., bears N. 24½° E., 38 lks. dist., with healed double blaze.

A fir 20 ins. diam., bears S. 69½° E., 21 lks. dist., with healed double blaze.

A fir, 18 ins. diam., bears S. 39½° W., 37½ lks. dist., with healed double blaze.

A root hole, with down fir, 18 ins. diam., bears N. 18° W., 9 lks. dist., with scribe marks T27S R3W CS BT visible on opened blaze.

and the remains of bearing trees mkd. by Corbin

A fir stump, 6 ins. diam., bears N. 60½° E., 13 lks. dist., with scribe marks T27S R3W S3 BT visible on partially healed blaze.