

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 3,
T. 27 S., R. 3 W., Willamette Meridian, Oregon

17963

CHAINS

T 26 S R 3 W
 $\frac{1}{4}$ $\frac{S 34}{S 3}$
 T 27 S
 1958

from which bearing trees mkd. by Corbin

A fir, 12 ins. diam., bears S. $38\frac{1}{2}^\circ$ E.,
40 lks. dist., with healed blaze.

A cedar, 20 ins. diam., bears N. $50\frac{3}{4}^\circ$ W.,
70 lks. dist., with healed blaze.

Corner is located at intersection of fences, extending
N. and E.

From the $\frac{1}{4}$ sec. cor. of secs. 2 and 3.

S. $89^\circ 06'$ W., on the E. and W. center line of sec. 3.

Ascend over broken NE. slope.

19.94

Point for the center E $\frac{1}{16}$ sec. cor. of sec. 3.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

C $\frac{E 1/16}{S 3}$ C
 1984

from which

A fir, 13 ins. diam., bears S. 14° W., 59 lks.
dist., mkd. CE $\frac{1}{16}$ S3 BT.

A sugar pine, 22 ins. diam., bears N. 36° W.,
48 lks. dist., mkd. CE $\frac{1}{16}$ S3 BT.

From this point, Douglas County Surveyors Office
horizontal control station "JIM 1972", bears
S. $27^\circ 56'$ E., 16.84 chs. dist., monumented with a
brass tablet, 3 ins. diam., firmly set in concrete,
with top mkd. DOUGLAS COUNTY SURVEYORS OFFICE JIM 1972.

Ascend over broken NE. slope.

29.25

Gravelled road, 15 lks. wide, bears N. 45° W. and
S. 45° E.

39.88

The center $\frac{1}{4}$ sec. cor. of sec. 3.

Ascend over broken NE. slope.

60.06

Point for the center W $\frac{1}{16}$ sec. cor. of sec. 3.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

C $\frac{W 1/16}{S 3}$ C
 1984