

County Surveyor's Record, Douglas County, Oregon

17988 Dependent Resurvey, Portion of the Subdivisional Lines
T. 28 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

- 54.45 Gravelled road, 20 lks. wide, bears N. 5° E. and S. 5° W.
- 56.30 Powerline, 2 wire service line, bears N. 10° W. and S. 10° E.
- 59.30 Creek, 5 lks. wide, course N.; asc. over broken E. slope.
- 79.77 The cor. of secs. 1, 6, 7, and 12, on the W. bdy. of the tp., perpetuated and recorded by James W. Byron, Douglas County Surveyor, in 1957, from original evidence no longer in existence, further perpetuated and recorded by Gary L. Langlitz, Deputy County Surveyor, in 1974, monumented with an iron post, 1½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

	T 28 S		
R	S 1	S 6	R
5	S 12	S 7	4
W	1957		W

from which the remains of bearing trees mkd. by Byron

A root hole, bears N. 13° E., 133 lks. dist., alongside of which is a down madrone, 20 ins. diam., with fragmentary scribe marks visible on burned blaze.

A root hole, bears S. 79° E., 41 lks. dist., no marks visible.

and bearing trees mkd. by Langlitz

A madrone, 7 ins. diam., bears N. 52° E., 68 lks. dist., with scribe marks T28S R4W S6 CS BT visible on open blaze.

A fir, 16 ins. diam., bears S. 14½° W., 255 lks. dist., with healed double blaze.

A fir, 9 ins. diam., bears N. 56° W., 13½ lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

and a bearing tree mkd. by person(s) unknown.

A madrone, 7 ins. diam., bears S. 9½° E., 8 lks. dist., with healed double blaze.

The corner is located N. 40° E., 20 lks. dist., from a fence corner, barbed wire fences extending N., E., and S.

Land, mountainous.

Soil, rocky clay.

Timber, fir, alder, maple, yew, madrone, ash, cedar, chinquapin, oak, and cherry; undergrowth, poison oak, blackberry, salal, arrowwood, hazel, vine maple, huckleberry, ferns and young timber.