

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **17997**
T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS	
1.70	Spur, slopes SE.; asc. along E. slope.
5.30	Top of ascent, slopes E.; desc. over NE. slope.
10.90	Creek, 2 lks. wide, course S. 85° E.; asc. over SE. slope.
15.00	Spur, slopes E.; desc. over NE. slope.
17.05	Ravine, drains E.; asc. over SE. slope.
19.86	Point for the S 1/16 sec. cor. of secs. 22 and 23. Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> S 1/16 S 22 S 23 1984 </div> from which <div style="margin-left: 40px;"> A fir, 41 ins. diam., bears N. 60° E., 45 lks. dist., mkd. S 1/16 S23 BT. A fir, 15 ins. diam., bears N. 55¼° W., 41½ lks. dist., mkd. S 1/16 S22 BT. </div> From this point, a point established by person(s) unknown, bears N. 4° 45' W., 0.195 chs. dist., monumented with an iron pipe, ½ in. diam., firmly set, projecting 2 ins. above ground. Continue ascent over SE. slope.
20.95	Spur, slopes E.; desc. over NE. slope.
24.20	Creek, 2 lks. wide, course S. 50° E.; asc. over SE. slope.
32.35	Spur, slopes E.; desc. over NE. slope.
38.05	Gravelled road, 20 lks. wide, bears N. 55° W. and S. 55° E.
39.10	Creek, 2 lks. wide, course S. 60° E.; asc. over SW. slope.
39.72	The 1/4 sec. cor. of secs. 22 and 23, monumented with an iron post, 1 in. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd. <div style="text-align: center;"> T 22 ¼ S 23 1953 </div> from which a bearing tree mkd. by Tillman and Gawron <div style="margin-left: 40px;"> A double top maple, 33 ins. diam., bears S. 45° E., 74 lks. dist., no marks visible on decayed blaze. (Record, 70 lks.) </div> and a new bearing tree <div style="margin-left: 40px;"> An alder, 10 ins. diam., bears S. 28½° W., 100 lks. dist., mkd. ¼ S22 BT. </div>