

County Surveyor's Record, Douglas County, Oregon

18008

Subdivision of Section 22,
T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

E 1/16 $\frac{S\ 22}{S\ 27}$
1982

from which bearing trees mkd. by Wofford

A hemlock, 25 ins. diam., bears S. $34\frac{1}{2}^\circ$ W., 31 lks. dist., with scribe marks E 1/16 S27 BT visible on partially healed blaze.

An alder, 18 ins. diam., bears N. $42\frac{1}{2}^\circ$ W., 45 lks. dist., with scribe marks E 1/16 S22 BT visible on bark.

N. $0^\circ 36'$ E., on the N. and S. center line of the SE 1/4 of sec. 22.

Ascend over SW. slope, through ehavy timber and dense undergrowth.

3.95 Spur, slopes S. 60° W.; desc. over NW. slope.

5.95 Creek, 1 lk. wide, course S. 60° W.; asc. over SW. slope.

11.65 Spur, slopes W.; desc. over NW. slope.

16.05 Bottom of descent, slopes W.; asc. over SW. slope.

19.915 Point for the SE 1/16 sec. cor. of sec. 22, at intersection with the E. and W. center line of the SE 1/4.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

SE 1/16 S22
1984

from which

A fir, 33 ins. diam., bears S. $34\frac{1}{2}^\circ$ E., 112. lks. dist., mkd. SE 1/16 S22 BT.

A fir, 5 ins. diam., bears N. 62° W., $32\frac{1}{2}$ lks. dist., mkd. X BT.

Continue ascent over SW. slope.

24.60 Gravelled road, 25 lks. wide, bears N. 50° W. and S. 60° E.

28.65 Ridge, bears NW. and SE.; desc. over NE. slope.

39.81 The center E 1/16 sec. cor. of sec. 22.

From the S 1/16 sec. cor. of secs. 22 and 23.

S. $89^\circ 25'$ W., on the E. and W. center line of the SE 1/4 of sec. 22.

Ascend over SE. slope, through ehavy timber and dense undergrowth.

13.55 Ridge, bears N. and S.; desc. over SW. slope.