

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the
 Subdivisional Lines, T. 24 S., R. 4 W.,
 18020 Willamette Meridian, Oregon

CHAINS

Beginning at the cor. of secs. 2, 3, 34, and 35, on the south boundary of the Tp., monumented with an iron pipe, 2 ins. diam., firmly set, projecting 12 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE
 T 24 S
 S 34 | S 35 R
 S 3 | S 2 4
 T 25 S
 1963

from which the remaining original bearing trees

A white oak, 26 ins. diam., bears N. 5° E.,
 465 lks. dist., with fragmentary scribe
 marks visible on opened blaze.

A white oak, 23 ins. diam., bears S. 10° E.,
 650 lks. dist., with scribe marks R4 visible
 on opened blaze.

A white oak, 21 ins. diam., bears S. 11½° W
 338 lks. dist., with fragmentary scribe
 marks visible on opened blaze.
 (Record, S. 7½° W.)

and bearing trees mkd. by Milo E. Godfrey, Deputy County
 Surveyor in 1963.

A white oak, 19 ins. diam., bears S. 50° E.,
 96 lks. dist., with healed blaze.

A fir, 28 ins. diam., bears S. 75° W.,
 100 lks. dist., with healed blaze.

An incense cedar, 45 ins. diam., bears
 N. 51° W., 46 lks. dist., with healed
 blaze.

North, bet. secs. 34 and 35, marking and blazing the true
 line.

Ascend over SW. slope, through light timber and moderate
 undergrowth, along barbed wire fence extending generally
 N. and S.

5.55 Spur, slopes N. 80° W.; desc. over NW. slope.

19.88 Point for the S 1/16 sec. cor. of secs. 34 and 35.

From this point, the S 1/16 sec. cor. of secs. 34 and
 35, erroneously established by Akin, in 1972, bears
 S. 0° 43' E., 0.64 chs. dist., set, marked and witnessed
 as described in the official record.

Remove the iron post, destroy the marks on the trees and
 at the true corner point

Reset the iron post, 28 ins. long, 2½ ins. diam., 24 ins.
 in the ground, with brass cap mkd.

S 1/16
 S 34 | S 35
 1985
 1972