

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the
 Subdivisional Lines, T. 24 S., R. 4 W., 18023
 Willamette Meridian, Oregon

CHAINS							
	<p>A fir stump, 18 ins. diam., bears S. 33° W., 18 lks. dist., with healed blaze.</p> <p>A fir, 17 ins. diam., bears N. 12° W., 27 lks. dist., with healed blaze.</p> <p>and a new bearing tree</p> <p>A fir, 26 ins. diam., bears S. 13½° E., 179 lks. dist., mkd. ¼ S35 BT.</p> <p>S. 89° 45' W., bet. secs. 26 and 35.</p> <p>Ascend over SE. slope, through moderate timber and dense undergrowth.</p>						
4.50	Top of ascent, slopes SW.; desc. over NW. slope.						
19.86	<p>Point for the W 1/16 sec. cor. of secs. 26 and 35.</p> <p>From this point, the W 1/16 sec. cor. of secs. 26 and 35, erroneously established by Akin, in 1972, bears S 12° 10' E., 0.16 chs. dist., set, marked, and witnessed as described in the official record.</p> <p>Remove the iron post, destroy the marks on the trees and at the true corner point</p> <p>Reset the iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto;"> <tr> <td style="padding: 0 10px;">S 1/16</td> <td style="border-left: 1px solid black; padding: 0 5px;"> <table style="border-collapse: collapse; margin: auto;"> <tr> <td style="padding: 0 5px;">S 26</td> <td style="border-bottom: 1px solid black; padding: 0 5px;"></td> </tr> <tr> <td style="padding: 0 5px;">S 35</td> <td style="padding: 0 5px;"></td> </tr> </table> </td> </tr> </table> <p style="margin: 0;">1985 1972</p> </div> <p>from which</p> <p>A fir, 10 ins. diam., bears N. 3° E., 96 lks. dist., mkd. W 1/16 S26 BT.</p> <p>A fir, 7 ins. diam., bears S. 40¼° E., 82 lks. dist., mkd. W 1/16 S35 BT.</p>	S 1/16	<table style="border-collapse: collapse; margin: auto;"> <tr> <td style="padding: 0 5px;">S 26</td> <td style="border-bottom: 1px solid black; padding: 0 5px;"></td> </tr> <tr> <td style="padding: 0 5px;">S 35</td> <td style="padding: 0 5px;"></td> </tr> </table>	S 26		S 35	
S 1/16	<table style="border-collapse: collapse; margin: auto;"> <tr> <td style="padding: 0 5px;">S 26</td> <td style="border-bottom: 1px solid black; padding: 0 5px;"></td> </tr> <tr> <td style="padding: 0 5px;">S 35</td> <td style="padding: 0 5px;"></td> </tr> </table>	S 26		S 35			
S 26							
S 35							
25.50	Ravine, drains S. 70° W.; asc. over SE. slope.						
26.50	Spur, slopes S. 30° W.; desc. over NW. slope.						
35.00	Barbed wire fence, bears N. and S.; also leave timber, edge bears N. and S.						
37.30	Long Valley Creek, 2 lks. wide, course S.; asc. over SE. slope.						
39.72	<p>The cor. of secs. 26, 27, 34, and 35.</p> <p>Land, mountainous. Soil, rocky clay loam Timber, fir, hemlock, alder, madrone, white oak, black oak, cedar, dogwood, and maple; undergrowth, salal, hazel, fern, poison oak, and vine maple.</p>						
14.70	<p>N. 0° 14' E., bet. secs. 26 and 27.</p> <p>Ascend over SE. slope, through scattering timber and light undergrowth.</p>						
14.90	Gravel road, 15 lks. wide, bears N. 60° W. and S. 60° E.						
14.90	Woven wire fence, bears N. 60° W. and S. 60° E.						