

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the
Subdivisional Lines, T. 24 S., R. 4 W.,
Willamette Meridian, Oregon

18024

CHAINS

17.30

Barbed wire fence, bears E. and W.; enter moderate timber and dense undergrowth.

30.45

Spur, slopes N. 45° E.; desc. over NW. slope.

39.76

The 1/4 sec. cor. of secs. 26 and 27, monumented with an iron post, 2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S
 $\frac{1}{4}$ S | S
 27 | 26
 R 4 W
 1963

from which the remains of the original bearing trees

A roothole, bears N. 75° E., 38 lks. dist.,

A fir snag, 36 ins. diam., bears S. 57° W.,
32 lks. dist., no marks visible.

and bearing trees mkd. by Milo E. Godfrey, Deputy County Surveyor in 1963

A black oak, 12 ins. diam., bears N. 14° E.,
36 lks. dist., with healed blaze.

A fir, 10 ins. diam., bears N. 46° W., 26 lks.
dist., with healed blaze.

Land mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, alder, madrone, white oak, black oak, cedar, dogwood, maple; undergrowth, salal, hazel, fern, poison oak, and vine maple.

From the cor. of secs. 26, 27, 34, and 35.

N. 89° 57' W., bet. secs. 27 and 34.

Ascend over SE. slope, through open field.

0.40

Gravel road, 15 lks. wide, bears N. and S.

5.85

Enter moderate timber and dense undergrowth, edge bears N. and S.

19.00

Barbed wire fence, bears N. 20° E. and S. 20° W.; also spur ridge, bears same; desc. over NW. slope.

31.20

Creek, 2 lks. wide, course N.; asc. over NE. slope.

37.00

Spur, slopes S. 45° E.; desc. over NW. slope.

39.68

The 1/4 sec. cor. of secs. 27 and 34, monumented with an iron post, 2 ins. diam., firmly set, projecting 9 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S
 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{27}{34}$
 R 4 W
 1963