

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the
Subdivisional Lines, T. 24 S., R. 4 W.,
Willamette Meridian, Oregon

18025

CHAINS

from which the remains of an original bearing tree

A madrone rootcrown, size indeterminate, bears
S. 76° W., 31 lks. dist.,

and bearing trees mkd. by Milo E. Godfrey, Deputy County
Surveyor in 1963

A fir, 20 ins. diam., bears N. 31° E., 33 lks.
dist., with healed blaze.

A fir, 11 ins. diam., bears S. 35° W., 23 lks.
dist., with healed blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, alder, madrone, white oak, black
oak, cedar, dogwood, and maple; undergrowth, salal,
hazel, fern, poison oak, and vine maple.

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 24 S., R. 4 W., Willamette Meridian, Oregon

(Restoring the 1896-97 survey by Oscar F. Thiel,
and the 1979 resurvey by James E. Jelley)

From the cor. of secs. 3, 4, 9, and 10, monumented with
an iron post, 1¼ ins. diam., firmly set, projecting 8
ins. above ground, with brass cap mkd.

COUNTY SURVEYOR OFFICE

T 24 S R 4 W
S 4 | S 3
S 9 | S 10
1961

from which the remains of the original bearing trees

A cedar stump, 36 ins. diam., bears N. 36½° E.,
36 lks. dist., no marks visible.

A cedar snag, 40 ins. diam., bears S. 88° E.,
88 lks. dist., with healed blaze.

A cedar stump. 40 ins. diam., bears N. 33° W.,
54 lks. dist., with fragmentary scribe marks
visible on opened blaze.

and bearing trees mkd. by James W. Byron, Deputy County
Surveyor in 1961

A hemlock, 11 ins. diam., bears S. 10¼° W.,
73½ lks. dist., with healed blaze.

A hemlock, 16 ins. diam., bears N. 78° W.,
35 lks. dist., with healed blaze.

A hemlock, 16 ins. diam., bears N. ½° W.,
73½ lks. dist., with healed blaze.

and a bearing tree mkd. by Milo E. Godfrey, Deputy County
Surveyor in 1963

A cedar, 42 ins. diam., bears S. 38° E.,
81 lks. dist., with healed blaze.