

# County Surveyor's Record, Douglas County, Oregon

**18048**

Subdivision of Section 33, T. 20 S., R. 7 W.,  
Willamette Meridian, Oregon

CHAINS	
46.90	Gravelled road, 20 lks. wide, bears N. 30° W. and S. 65° E. in a curve.
78.19	The 1/4 sec. cor. of secs. 32 and 33.
	From the center E 1/16 sec. cor. of sec. 33.
	N. 0° 17' W., on the N. and S. center line of the NE 1/4 of sec. 33.
	Descend over broken NE. slope, through heavy timber and dense undergrowth.
24.15	Creek, 12 lks. wide, course NE.; asc. over SE. slope.
40.18	The E 1/16 sec. cor. of secs. 28 and 33.
	Subdivision of Section 34, T. 20 S., R. 7 W., Willamette Meridian, Oregon
	From the 1/4 sec. cor. of sec. 34 only, on the S. bdy. of the Tp.
	N. 0° 28' W., on the N. and S. center line of sec. 34.
	Ascend over broken SW. slope, through heavy timber and dense undergrowth.
4.65	Spur, slopes S. 75° E.; desc. over broken NE. slope.
13.40	Ridge, bears N. 40° E. and S. 40° W.; desc. over broken NW. slope, changing to NE. slope.
32.90	Creek, 3 lks wide, course N. 60° W.; asc. over broken SW. slope.
35.70	Spur, slopes S. 85° W.; desc. over NW. slope.
37.10	Creek, 3 lks. wide, course S. 70° W.; asc. over broken SW. slope.
39.64	Point for the center 1/4 sec. cor. of sec. 34, at intersection with the E. and W. center line.
	Set an aluminum post, 28 ins. long 2½ ins. diam., 24 ins. in the ground, with aluminum cap mkd.
	T 20 S R 7 W C ¼ S 34 1983
	from which
	A cedar, 23 ins. diam., bears S. 30¼° E., 59 lks. dist., mkd. C¼ S34 BT.
	A fir, 8 ins. diam., bears N. 54° W., 76 lks. dist., mkd. C¼ S34 BT.
	Ascend over broken SW. slope.
45.75	Spur, slopes N. 70° W., desc. over broken NW. slope.
47.75	Creek, 2 lks. wide, course S. 65° W.; asc. over broken SE. slope.