

# County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 34, T. 20 S., R. 7 W.,  
Willamette Meridian, Oregon

18049

CHAINS										
61.00	Spur, slopes S. 70° W.; desc. over broken NW. slope.									
75.95	Smith River, 65 lks. wide, course S. 80° W.; asc. over broken SW. slope.									
79.44	<p>The 1/4 sec. cor. of secs. 27 and 34, perpetuated and recorded by Wilford N. Haines, Registered Land Surveyor No. 239, in 1965, monumented with a 1 in. "T" shaped iron rod, firmly set, projecting 18 ins. above ground, from which the remains of the original bearing trees:</p> <p style="margin-left: 40px;">A roothole, bears N.23° E., 105 lks. dist.</p> <p style="margin-left: 40px;">A sawed cedar stump, 60 ins. diam., bears S. 28° W., 55 lks. dist., no marks visible.</p> <p>and bearing trees mkd. by Haines</p> <p style="margin-left: 40px;">A fir, 16 ins. diam., bears N. 48° E., 39½ lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 28 ins. diam., bears S. 51° E., 11½ lks. dist., with healed blaze.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron rod, with brass cap mkd.</p> <div style="text-align: center; margin-top: 10px;"> <table style="border: none;"> <tr> <td>T 20</td> <td>S R 7 W</td> <td rowspan="4" style="font-size: small; vertical-align: middle;"> <i>FD OK 10/95 BY EDWARDS M 122-71 FD OK 6/1998 Edwards M130-2</i> </td> </tr> <tr> <td></td> <td>S 27</td> </tr> <tr> <td></td> <td>S 34</td> </tr> <tr> <td></td> <td>1983</td> </tr> </table> </div>	T 20	S R 7 W	<i>FD OK 10/95 BY EDWARDS M 122-71 FD OK 6/1998 Edwards M130-2</i>		S 27		S 34		1983
T 20	S R 7 W	<i>FD OK 10/95 BY EDWARDS M 122-71 FD OK 6/1998 Edwards M130-2</i>								
	S 27									
	S 34									
	1983									
	<p>From the 1/4 sec. cor. of secs. 34 and 35.</p> <p>S. 88° 09' W., on the E. and W. center line of sec. 34.</p> <p>Descend over NW. slope, through heavy timber and dense undergrowth.</p>									
9.10	Ravine, drains N. 60° E.; asc. over SE. slope.									
17.90	Spur, slopes N.; desc. over broken SW. slope.									
39.41	<p>The center 1/4 sec. cor. of sec. 34.</p> <p>Descend over broken SW. slope.</p>									
46.65	Creek, 4 lks. wide, course N.; asc. over broken NE. slope.									
72.05	Spur, slopes N. 40° E.; desc. over broken NW. slope.									
79.61	The 1/4 sec. cor. of secs. 33 and 34.									
<p><b>GENERAL DESCRIPTION</b></p> <p>The lands included in the foregoing survey are located approximately 13 miles northwesterly of the town of Drain, Oregon. Access into the area is via a paved county road extending along the Smith River and several gravelled and dirt roads branching from it into the area.</p> <p>The area is drained by the Smith River and its tributaries with numerous seasonal drainages. The elevations range from about 630 feet above sea level at</p>										