

County Surveyor's Record, Douglas County, Oregon

18053

Dependent Resurvey of a Portion of the South Boundary,
T. 20 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

Beginning at the cor. of secs. 35 and 36 only, perpetuated by Wilford N. Haines, Registered Land Surveyor No. 239, during an unrecorded survey, and further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1958, monumented with a "T" shaped iron rod, 1 in. diam., firmly set, projecting 6 ins. above ground, with washer mkd.

WILFORD N HAINES
239
SURVEY POINT
DRAIN OR

from which the remains of an original bearing tree

A decayed fir stump, 36 ins. diam., bears
S 45° E., 38 lks. dist., no marks visible.

and the remains of bearing trees mkd. by Byron

A fir, 18 ins. diam., bears N. 54° E., 68
lks. dist., with healed double blaze.

A sawed fir stump, 26 ins. diam., bears
N. 62° E., 26 lks. dist., no marks visible.

A fir, 17 ins. diam., bears N. 68½° W., 18
lks. dist., with fragmentary scribe marks
visible on partially healed double blaze.
and a bearing tree mkd. by McDonald

A fir, 17 ins. diam., bears N. 52° E., 74 lks.
dist., with healed blaze. (Record N.51° E.,
75 lks.)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, directly over iron rod, with brass cap
mkd.

T 20 S R 6 W
S 35 | S 36
S 2
T 21 S R 6 W
1984

FD. OK 7-9A
BY WELLMAN
M 120-55
FD. OK
L. ROBERTS
12/92
M 116-43
C.S. 63/149

S. 89° 55' W., on the S. bdy. of sec. 35, marking and
blazing the true line.

Descend over NW. slope, through heavy timber and dense
undergrowth.

- 20.10 Redford Creek, 5 lks. wide, course S. 65° W.; asc. over SE. slope.
- 24.85 Gravelled road, 15 lks. wide, bears N. 50° E. and S. 50° W.
- 28.45 Spur, slopes S. 35° E.; desc. over SW. slope.
- 28.95 Power transmission line, bears N. 35° W. and S. 35° E.
- 31.85 Smith River Road, paved, 40 lks. wide, bears N. 55° W. and S. 45° E.