

County Surveyor's Record, Douglas County, Oregon

18058

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 21 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

44.265

Intersect the S. bdy. of T. 20 S., R. 6 W.

True point for the closing cor. of secs. 2 and 3.

Set an iron post, 30 ins. long, 2 ins. diam., with magnetic, plastic breakaway base, 24 ins. in the ground, with brass cap mkd.

*FD. OK
12/20/82
M.H. - 43
C.S. 6/2/84*

T 20 S R 6 W
S 35
S 3 | S 2
C C
T 21 S R 6 W
1984

from which

A fir, 8 ins. diam., bears S. $31\frac{1}{2}^\circ$ E., 93 lks. dist., mkd. T21S R6W S2 CC BT.

A fir, 6 ins. diam., bears S. $70\frac{1}{2}^\circ$ W., 47 lks. dist., mkd. T21S R6W S3 CC BT.

From this point, a point established by Wilford N. Haines, Registered Land Surveyor No. 239, during an unrecorded survey, bears S. $30\frac{1}{2}^\circ$ E., 0.07 chs. dist., monumented with a "T" shaped iron, 1 in. diam., firmly set, projecting 4 ins. above ground, with washer mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN OR, from which a bearing tree mkd. by Haines:

A fir, 24 ins. diam., bears N. 71° E., 158 lks. dist., with healed blaze.

From this same point, the cor. of secs. 34 and 35, T. 20 S., R. 6 W., bears S. $89^\circ 55'$ W., 3.61 chs. dist., hereinbefore described.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, yew, maple, alder, madrone, dogwood, ash, and willow; undergrowth, Oregon grape, salal, ferns, arrowwood, blackberry, vine maple, hazel, and young timber.

From the cor. of secs. 2, 3, 10, and 11, perpetuated and recorded by Wilford N. Haines, Registered Land Surveyor No. 239, in 1961, from original evidence no longer in existence, monumented with a "T" shaped iron rod, 1 in. diam., firmly set, projecting 6 ins. above ground, with washer mkd.

WILFORD N HAINES
239
SURVEY POINT
DRAIN OR

At the corner point

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, directly over iron rod, with brass cap mkd.