

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, 18077
T. 22 S., R. 7 W., Willamette Meridian, Oregon

| CHAINS | T 22 S R 7 W 1/4 S 27/S 26 1984 |
|--------|---|
| | <hr style="width: 20%; margin: auto;"/> |
| | N. 0° 12' W., beginning new measurement. |
| | Ascend over broken SW. slope |
| 14.65 | Spur, slopes N. 35° W., desc. over broken NE. slope. |
| 31.15 | Creek, 5 lks. wide, course N. 15° W.; desc. over NW. slope. |
| 33.30 | Dirt road, 15 lks. wide, bears N. 40° E. and S. 75° W. |
| 37.91 | The cor. of secs. 22, 23, 26, and 27, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd. |
| | 22 S R 7 W <u>S 22/S 23</u> S 27/S 26 1965 |
| | from which the remains of bearing trees mkd. by Chapman and Nicklin |
| | A burned fir stump, 18 ins. diam., bears N. 28° E., 38 lks. dist., no marks visible. |
| | A burned fir stump, 42 ins. diam., bears S. 21° W., 40 lks. dist., no marks visible. (Record, S. 24° W.) |
| | A burned and down fir, 36 ins. diam., bears N. 45° W., 92 lks. dist., no marks visible. |
| | and the remains of bearing trees mkd. by Wilford N. Haines, Registered Land Surveyor, No. 239, in 1957 |
| | A root hole, bears N. 30° E., 52 lks. dist., with a down fir alongside, 10 ins. diam., with scribe marks T22S R7W S23 BT visible on open blaze. |
| | A root hole, bears S. 66° E., 42 lks. dist., with a down fir alongside, 16 ins. diam., with scribe marks T22S R7W S26 BT visible on partially healed blaze. |
| | and the remains of bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1960 |
| | A fir, 18 ins. diam., bears N. 19° E., 152 lks. dist., with healed blaze. |
| | A fir stump, 52 ins. diam., bears S. 34° W., 62 lks. dist., with scribe marks T22S R7W S27 CS BT visible on partially healed blaze. |
| | A fir stump, 18 ins. diam., bears N. 9° W. 168 lks. dist., no marks visible |
| | and bearing trees mkd. by Jelley and Beck |