

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 23,
T. 22 S., R. 7 W., Willamette Meridian, Oregon

18081

CHAINS	
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 22 W R 7 W C 1/4 S 23 1984</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 4 ins. diam., bears N. 32° E., 4 1/2 lks. dist., mkd. X BT.</p> <p style="padding-left: 40px;">A fir, 7 ins. diam., bears S. 41 3/4° W., 67 lks. dist., mkd. C 1/4 S23 BT.</p> <p>Ascend over broken SE. slope.</p>
50.85	Spur, slopes S. 80° E.; desc. over NE. slope.
53.55	Ravine, drains S. 85° E.; asc. over SE. slope.
56.95	Spur, slopes S. 85° E.; desc. over broken NE. slope.
59.96	<p>Point for the center N 1/16 sec. cor. of sec. 23.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">C N 1/16 S 23 C 1984</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S. 45 3/4° E., 27 1/2 lks. dist., mkd. CN 1/16 S23 Bt.</p> <p style="padding-left: 40px;">A fir, 26 ins. diam., bears S. 52° W., 24 lks. dist., mkd. CN 1/16 S23 BT.</p> <p>Descend over broken NE. slope.</p>
66.20	Creek, 8 lks, wide, course N. 50° W.; asc. over broken SW. slope.
71.05	Dirt road, 25 lks. wide, bears N. 70° W. and S. 50° E.
76.15	Creek, 3 lks. wide, course S. 70° W.; asc. over broken SW. slope.
80.78	<p>The 1/4 sec. cor. of secs. 14 and 23, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">T 22 S R 7 W 1/4 S 14 S 23 1965</p> <p>from which the remaining original bearing tree</p> <p style="padding-left: 40px;">A fir, 67 ins. diam., bears N. 31° E., 83 lks. dist., remarked by Haines in 1958 with scribe marks 1/4 S14 363 BT visible on bark blaze.</p>