

# County Surveyor's Record, Douglas County, Oregon

**18094** Dependent Resurvey, Portion of Subdivisional lines  
T. 23 S., R. 8 W., Willamette Meridian, Oregon

**CHAINS**

Cor. is located at SE. cor. of logged area, edge bears irregularly N. and W.

Continue descent over broken SW. slope, along S. edge of logged area.

29.50 Enter logged area, edge bears E. and S.

39.97 Point for the  $\frac{1}{4}$  sec. cor. of secs. 26 and 35, at proportionate dist.; there is no remaining evidence of the original cor.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 8 W  
 $\frac{1}{4}$  S 26  
S 35  
1984

from which

A fir, 8 ins. diam., bears N.  $79\frac{3}{4}^\circ$  E., 77 lks. dist., mkd.  $\frac{1}{4}$  S26 BT.

A fir, 8 ins. diam., bears S.  $89^\circ$  W., 136 lks. dist., mkd.  $\frac{1}{4}$  S35 BT.

Continue descent over SW. slope.

48.35 Gravelled road, 20 lks. wide, bears NW. and SE.; enter timber, edge bears same.

48.75 Waggoner Creek, 20 lks. wide, course irregularly S.  $85^\circ$  E; asc. along creek bottom and broken N. slope.

79.94 The cor. of secs. 26, 27, 34, and 35, perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1964, monumented with an iron post,  $1\frac{1}{4}$  ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 23 S  
S 27 | S 26  
S 34 | S 35  
R 8 W  
1964

from which the remaining original bearing tree

A cedar, 49 ins. diam., bears N.  $43^\circ$  E., 17 lks. dist., with healed blaze.  
(Record and to face, 14 lks. dist.)

and the remains of bearing trees mkd. by Godfrey

A cedar, 22 ins. diam., bears S.  $16^\circ$  E., 36 lks. dist., with healed blaze.

A root hole, bears S.  $24^\circ$  W., 70 lks. dist., with down cedar, 48 ins. diam., alongside with healed blaze.

No other suitable trees available.