

County Surveyor's Record, Douglas County, Oregon

18095

Dependent Resurvey, Portion of Subdivisional Lines,
T. 23 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

Corner is located on steep N. slope, 1 chain south of Waggoner Creek, 20 lks. wide, course E.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, alder, and maple; undergrowth, blackberry, arrowwood, fern, vine maple, and poison oak.

Subdivision of Section 35,
T. 23 S., R. 8 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of sec. 35 only, perpetuated and recorded by Vernon R. Tracy, Deputy County Surveyor, in 1967, monumented with an iron post, 1½ ins. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.

T 23 S
1/4 — S 35 — R 8 W
T 24 S
1967

from which the remains of an original bearing tree

A fir stump, 46 ins. diam., bears N. 71° W.,
14 lks. dist., with scribe marks ¼ S visible on open blaze.

and remains of bearing trees mkd. by Tracy

A root hole, bears N. 30° E., 32 lks. dist.,
with a down fir alongside, 15 ins. diam.,
with healed blaze.

A root hole, bears N. 30½° W., 33 lks. dist.,
with a down hemlock alongside, 11 ins. diam.,
with healed blaze.

and a new bearing tree

A hemlock, 6 ins. diam., bears N. 58° E.,
29 lks. dist., mkd. ¼ S35 BT.

No other suitable trees available.

Cor. is located in logged area, in head of ravine,
drains NE.

North, on the N. and S. center lien of sec. 35, marking
and blazing the true line.

Descend over broken N. slope, through logged area and
dense undergrowth.

6.05 Ravine, drains NE.; asc. over broken SE. slope.

18.15 Gravelled road, 20 lks. wide, bears N. 30° E. and
S. 50° W., in curve; also spur, slopes NE.; enter
timber, edge bears N. 30° E. and S. 50° W.; desc. over
broken N. slope.