

County Surveyor's Record, Douglas County, Oregon

18111

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 30 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

COUNTY SURVEYORS OFFICE

T 30 S
WC 10 FT N
S 4 | S 3
S 9 | S 10
R 8 W
1965

from which the bearing trees mkd. by Tracy

A fir, 11 ins. diam., bears S. 87° E.,
84 lks. dist., with healed double blaze.

A hemlock, 15 ins. diam., bears S. 35° E.,
58 lks. dist., with healed double blaze.

A grand fir, 19 ins. diam., bears S. 55° W.,
42 lks. dist., with healed double blaze.

N. 0° 03' W., bet. secs. 3 and 4.

Descend over NE. slope, through heavy timber and dense undergrowth.

2.50 Gravelled road, 20 lks. wide, bears N. 85° E. and
S. 85° W.

7.05 Creek, 10 lks. wide, course N. 75° W.; asc. over SW.
slope.

19.00 Spur, slopes W.; desc. over NW. slope.

27.15 Berry Creek, 15 lks. wide, course N. 40° E.; asc. over
broken SE. slope.

39.46 Point for the 1/4 sec. cor. of secs. 3 and 4, at propor-
tionate distance; there is no remaining evidence of the
original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
24 ins. in the ground, with brass cap mkd.

T 30 S R 8 W
S 4 | ¹/₄ | S 3
1985

from which

A fir, 10 ins. diam., bears S. 33° E., 22
lks. dist., mkd. 1/4 S3 BT.

A fir, 7 ins. diam., bears S. 29° W., 9
lks. dist., mkd. 1/4 S4 BT.

Deposit a white "DEEP-1" magnetic marker at
base of stainless steel post.

Ascend over broken SE. slope.

40.90 Spur, slopes E.; desc. over broken NE. slope.

73.35 Berry Creek, 15 lks. wide, course NW.; asc. over SW.
slope.